



TAG #	BOTANICAL NAME	COMMON NAME	DBH (cm)	CNPY SPR (m)	COND.	REMARKS	PRES. STATUS
501	<i>Amelanchier canadensis</i>	Serviceberry	11	3	Fair		Remove
502	<i>Acer rubrum</i>	Red Maple	8	2	Terminal Decline	75% dead	Remove
503	<i>Amelanchier canadensis</i>	Serviceberry	10	4	Good	Planted high	Remove
504	<i>Acer ginnala</i>	Amur Maple	12	3	Poor	Frost crack, many dead branches	Remove
505	<i>Amelanchier canadensis</i>	Serviceberry	8	3	Good		Remove
506	N/A	N/A	5	1	Dead		Remove
507	<i>Amelanchier canadensis</i>	Serviceberry	8	4	Good		Remove
508	<i>Amelanchier canadensis</i>	Serviceberry	8	3	Good		Remove
509	<i>Acer ginnala</i>	Amur Maple	18	6	Fair	Exposed roots, slight damage to trunk	Remove
510	<i>Amelanchier canadensis</i>	Serviceberry	5	2	Good		Remove
511	<i>Amelanchier canadensis</i>	Serviceberry	8	4	Good		Remove
512	N/A	N/A	7	3	Dead		Remove
513	<i>Amelanchier canadensis</i>	Serviceberry	8	3	Good		Remove
514	<i>Acer ginnala</i>	Amur Maple	14	5	Good		Remove
515	<i>Acer ginnala</i>	Amur Maple	13	3	Good		Remove
516	<i>Acer ginnala</i>	Amur Maple	12	3	Good		Remove
517	<i>Acer ginnala</i>	Amur Maple	23	5	Fair	Measured at 0.3m height, co-dominant at 0.3m height	Remove
518	<i>Amelanchier canadensis</i>	Serviceberry	6	2	Poor	Few dead branches	Remove
519	<i>Amelanchier canadensis</i>	Serviceberry	3	1	Good		Remove
520	<i>Amelanchier canadensis</i>	Serviceberry	7	2	Poor	Poor vigor	Remove
521	<i>Amelanchier canadensis</i>	Serviceberry	7	2	Poor	Lean	Remove
522	<i>Gleditsia triacanthos</i>	Honeylocust	7	4	Good		Remove
523	<i>Gleditsia triacanthos</i>	Honeylocust	6	4	Good		Remove
524	<i>Gleditsia triacanthos</i>	Honeylocust	6	5	Good		Remove
525	<i>Gleditsia triacanthos</i>	Honeylocust	6	3	Good		Remove
526	<i>Gleditsia triacanthos</i>	Honeylocust	5	4	Good		Remove
527	<i>Gleditsia triacanthos</i>	Honeylocust	7	4	Good		Remove
528	<i>Gleditsia triacanthos</i>	Honeylocust	7	3	Good		Remove
529	<i>Gleditsia triacanthos</i>	Honeylocust	6	3	Good		Remove
530	<i>Gleditsia triacanthos</i>	Honeylocust	6	4	Fair	Damage at base	Remove
531	<i>Gleditsia triacanthos</i>	Honeylocust	13	6	Good		Remove
532	<i>Amelanchier canadensis</i>	Serviceberry	5	2	Fair	Insect damage in bark	Remove
533	<i>Amelanchier canadensis</i>	Serviceberry	6	2	Good		Remove
534	<i>Amelanchier canadensis</i>	Serviceberry	6	2	Good		Remove
535	<i>Pyrus sp.</i>	Pear	8	2	Fair		Remove
536	<i>Pyrus sp.</i>	Pear	10	2	Poor	Leader dead	Remove
537	<i>Pyrus sp.</i>	Pear	10	2	Fair	Slight dieback	Remove
538	<i>Pyrus sp.</i>	Pear	13	3	Fair		Remove
539	<i>Celtis occidentalis</i>	Hackberry	23	7	Good		Remove
540	<i>Acer saccharum</i>	Sugar Maple	6	3	Terminal Decline	80% dead	Remove
541	<i>Acer saccharum</i>	Sugar Maple	7	4	Fair		Remove
542	<i>Pyrus sp.</i>	Pear	13	4	Terminal Decline	90% dead, measured from 0.9m height	Remove
543	<i>Pyrus sp.</i>	Pear	12	3	Fair		Remove
544	<i>Pyrus sp.</i>	Pear	14	3	Fair		Remove
545	<i>Pyrus sp.</i>	Pear	12	3	Fair		Remove
546	<i>Pyrus sp.</i>	Pear	14	3	Fair		Remove
547	<i>Pyrus sp.</i>	Pear	15	3	Fair		Remove
548	<i>Gleditsia triacanthos</i>	Honeylocust	32	8	Good		Remove
549	<i>Gleditsia triacanthos</i>	Honeylocust	30	8	Good		Remove
550	<i>Acer saccharum</i>	Silver Maple	7	3	Poor	Slight damage to leader / trunk	Remove
551	<i>Gingko biloba</i>	Ginkgo	6	2	Good		Remove
552	<i>Gingko biloba</i>	Ginkgo	6	2	Good		Remove
553	<i>Picea pungens</i>	Colorado Spruce	18	3	Fair		Remove
554	<i>Picea pungens</i>	Colorado Spruce	15	3	Fair	Twist in stem	Remove
555	<i>Picea pungens</i>	Colorado Spruce	15	4	Dead		Remove
556	<i>Picea pungens</i>	Colorado Spruce	8	2	Dead		Remove
557	<i>Picea pungens</i>	Colorado Spruce	15	3	Poor	Dieback	Remove
558	<i>Picea pungens</i>	Colorado Spruce	15	3	Fair		Remove
559	<i>Picea pungens</i>	Colorado Spruce	12	3	Fair		Remove
560	<i>Picea pungens</i>	Colorado Spruce	13	3	Poor	Dieback	Remove
561	<i>Gleditsia triacanthos</i>	Honeylocust	15	5	Fair	Few dead branches	Remove
562	<i>Gleditsia triacanthos</i>	Honeylocust	15	4	Good		Remove
563	<i>Gleditsia triacanthos</i>	Honeylocust	13	4	Good		Remove
564	<i>Gleditsia triacanthos</i>	Honeylocust	19	6	Good		Remove
565	<i>Gleditsia triacanthos</i>	Honeylocust	26	10	Good		Remove
566	<i>Picea pungens</i>	Colorado Spruce	15	3	Fair		Remove
567	<i>Picea pungens</i>	Colorado Spruce	18	3	Fair		Remove
568	<i>Picea pungens</i>	Colorado Spruce	16	3	Fair		Remove
569	<i>Quercus alba</i>	White Oak	27	6	Good		Remove
570	<i>Celtis occidentalis</i>	Hackberry	12	5	Good		Remove
571	<i>Celtis occidentalis</i>	Hackberry	13	3	Good		Remove
572	<i>Pinus strobus</i>	White Pine	12	4	Good		Remove
573	<i>Pinus strobus</i>	White Pine	12	3	Good		Remove
574	<i>Celtis occidentalis</i>	Hackberry	10	3	Good		Remove
575	<i>Celtis occidentalis</i>	Hackberry	8	2	Good		Remove
576	<i>Celtis occidentalis</i>	Hackberry	10	3	Good		Remove
577	<i>Celtis occidentalis</i>	Hackberry	14	3	Good		Remove
578	<i>Quercus alba</i>	White Oak	28	3	Good		Remove
579	<i>Quercus alba</i>	White Oak	28	8	Good		Remove
580	<i>Picea pungens</i>	Colorado Spruce	17	3	Good		Remove
581	<i>Picea pungens</i>	Colorado Spruce	18	3	Good		Remove
582	<i>Picea pungens</i>	Colorado Spruce	17	3	Good		Remove
583	<i>Picea pungens</i>	Colorado Spruce	15	3	Good		Remove
584	<i>Picea pungens</i>	Colorado Spruce	20	3	Good		Remove
585	<i>Picea pungens</i>	Colorado Spruce	15	3	Good		Remove
586	<i>Picea pungens</i>	Colorado Spruce	14	3	Good		Remove
587	<i>Picea pungens</i>	Colorado Spruce	18	3	Good		Remove
588	<i>Picea pungens</i>	Colorado Spruce	15	3	Good		Remove
589	<i>Picea pungens</i>	Colorado Spruce	13	2	Good		Remove
590	<i>Picea pungens</i>	Colorado Spruce	18	3	Good		Remove
591	<i>Picea pungens</i>	Colorado Spruce	13	6	Good		Remove
592	<i>Picea pungens</i>	Colorado Spruce	14	6	Good		Remove
593	<i>Celtis occidentalis</i>	Hackberry	18	6	Good		Remove
594	<i>Celtis occidentalis</i>	Hackberry	16	6	Good		Remove
595	<i>Quercus alba</i>	White Oak	4.4	2	Poor	Main stem cut, two suckers now co-dominant stems at base	Remove
596	<i>Quercus alba</i>	White Oak	13	6	Good		Remove
597	<i>Celtis occidentalis</i>	Hackberry	18	5	Fair		Remove
598	<i>Celtis occidentalis</i>	Hackberry	16	5	Good		Remove
599	<i>Celtis occidentalis</i>	Hackberry	18	6	Good		Remove
600	<i>Celtis occidentalis</i>	Hackberry	15	5	Good		Remove
601	<i>Quercus alba</i>	White Oak	26	6	Good		Remove
602	<i>Quercus macrocarpa</i>	Bur Oak	19	6	Good		Remove
603	<i>Celtis occidentalis</i>	Hackberry	18	6	Good		Remove
604	<i>Celtis occidentalis</i>	Hackberry	22	6	Good		Remove
605	<i>Celtis occidentalis</i>	Hackberry	21	6	Good		Remove
606	<i>Quercus alba</i>	White Oak	25	8	Good		Remove
607	<i>Quercus alba</i>	White Oak	27	8	Good		Remove
608	<i>Gleditsia triacanthos</i>	Honeylocust	12	3	Good		Remove
609	<i>Gleditsia triacanthos</i>	Honeylocust	8	3	Good		Remove
610	<i>Celtis occidentalis</i>	Hackberry	6	2	Poor	Leader dead, slight dieback	Remove
611	<i>Gleditsia triacanthos</i>	Honeylocust	8	4	Good		Remove
612	<i>Acer rubrum</i>	Red Maple	10	4	Fair	Girdled stem at support stake	Remove
613	<i>Celtis occidentalis</i>	Hackberry	6	2	Fair	Few dead branches	Remove
859	<i>Ulmus pumila</i>	Siberian Elm	80	14	Fair	Codominant stems at 2m, within naturalized area	Preserve
860	<i>Celtis occidentalis</i>	Siberian Elm	13	3	Fair	Within naturalized area	Remove
861	<i>Celtis occidentalis</i>	Siberian Elm	15	3	Fair	Within naturalized area	Remove



NOTE: This drawing, as an instrument of service, is provided by The MBTW Group. The contractor shall check and verify all dimensions and report all error and omissions, to the Landscape Architect whose seal is affixed to this drawing, before proceeding with the work. This drawing is not to be scaled. All dimensions are in millimeters unless otherwise noted. Stake out all utilities prior to commencing work.

**Legend**

- PHASING LINE
- PROPERTY LINE
- - - TREE PROTECTION FENCING
- EXISTING TREE TO BE PRESERVED
- ⊗ EXISTING TREE TO BE REMOVED

NOTE: FOR INFORMATION PURPOSES ONLY  
 NOTE: REFER TO ARBORIST REPORT BY MBTW FOR SITE PHOTOS



INSPECTION CONDUCTED ON AUGUST 15, 2023  
 BY MIKE HUKZALEJ - ISA CERTIFIED ARBORIST No. ON-2408A

SURVEY INFORMATION PROVIDED BY JD BARNES AS OF SEPTEMBER 11, 2023

No	Date	Revisions	By
2	12-20-2024	REISSUED FOR ZBA / OPA	CKA
1	10-27-2023	ISSUED FOR ZBA / OPA	CKA

Association of Landscape Contractors  
 Member  
 Designated By: [Signature]  
 North Arrow

Project Name: 1101A, 1105, 1163 Kingston Road  
 Municipality: Town of Pickering  
 Sheet Title: Tree Inventory Plan

The MBTW Group  
 Job No: TRC148  
 Designated: [Signature]  
 Drawn: MH  
 Date: October 19, 2023  
 Scale: 1:1000  
 Drawing No.: TP-1

Community Planning  
 Urban Design  
 Landscape Architecture  
 235 Woodbine Avenue  
 Unit 1A  
 Toronto, Ontario  
 Canada M4E 1B8  
 Tel: (416) 448-7787  
 Fax: (416) 448-1903  
 E-mail: info@mbtw.com